



Jim Wildey

Materials Laboratory Division

National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800



National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Breakup Sequence Presentation

- Formation of the “Metallurgy and Structures/Sequencing Group”
- Description of wing center section
- Overall sequence with details on
 - Specific portions of the sequence and
 - Evidence of an overpressure event
- Video of reconstruction showing sequence



National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Metallurgy and Structures/Sequencing Group

- Group members from Boeing; TWA; ALPA; International Association of Machinists, Aerospace Workers, and Flight Attendants; and the Federal Aviation Administration
- The group's task was to identify how the airplane broke apart and where the breakup initiated
- The group examined structure at Calverton, Long Island







'87 5 30




National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800










National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Wing Center Section





National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

STA
1480




STA
1236



STA
1000



STA
800



STA
520



Right Side View

Forward





Nati
Inves

Front
Spar



Right Side View

Forward







National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Breakup Sequence

Spanwise beam 3 fractured at its upper end,
then
rotated forward







National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Breakup Sequence


Spanwise beam 3 fractured at its upper end,
then

rotated forward

Front spar fractured, progressed downward,
and

entered the fuselage at stringer 40R

Fuselage
Cracking
Initiation
Area





National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Breakup Sequence

Spanwise beam 3 fractured at its upper end, then rotated forward

Front spar fractured, progressed downward, and entered the fuselage at stringer 40R

“Early” fuselage fractures created a hole in the belly of the airplane

Additional fuselage fractures allowed release of the nose portion



National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Evidence of Overpressure

- Spanwise beam 3 fracturing and rotating forward
- Upward bulging of the upper skin panel
- Forward bulging of the front spar
- Downward pressure loads initiating fracture in fuselage at S40R



National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

STA
1480




STA
1236




STA
1000



STA
800



STA
520



WCS

Right Side View

Forward





National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Breakup Sequence

Spanwise beam 3 fractured at its upper end, then rotated forward

Front spar fractured, progressed downward, and entered the fuselage at stringer 40R

“Early” fuselage fractures created a hole in the belly of the airplane

Additional fuselage fractures allowed release of the nose portion

Main portion of the airplane (most of the wing center section, wings, aft fuselage, and tail) remained intact, then climbed and rolled

Main portion broke up further as speeds and loads increased during descent



National Transportation Safety Board

Investigation Into Trans World Airlines Flight 800

Conclusion

Breakup of the TWA flight 800 airplane initiated with the fracture of spanwise beam 3 as a result of an overpressure event within the center wing tank.



'87 5 30



National Transportation Safety Board
Investigation Into Trans World Airlines Flight 800